

**GEARSET Blender Motor Repair Kit**  
***Outside Air Blender Door Motor Gear and Lever Set***  
***/ Repair Kit for Heater Flap Control Stepper Motor***  
**Part No.:**

GEARSET

*Blender motor has 2 gears and a lever to open and close the door so fresh air can filter through the AC system. Gears and lever are made of plastic and with time get brittle and brake. If the gears or lever are broken the electric stepper motor will run, but the blender door will not move and this will cause the AC /Heating system not to operate properly, sending the System Error Message - Blender Door Motor Inoperable. Simple repair - gears go inside the housing of the stepper motor, lever goes on the outside. One set will repair one motor. Gears and lever are identical for the left and right side motors.*

*For Saab 9-5 Years 1998-2009*

